

**Materialprüfungsanstalt
Universität Stuttgart**
P.O. Box 80 11 40
70511 Stuttgart
Germany

MPA **MPA STUTTGART**
Otto-Graf-Institut
Materialprüfungsanstalt Universität Stuttgart



Investigation Report

Client:	PPG Deco Polska Spolka z o. o. ul. Kwidzynska 8 51-416 Wroclaw Poland
Order-No. (Client):	
Order-No. (MPA):	902 4499 000-02/Whr/Pi
Test Item:	Domalux Professional Poliuretan Aqua 1S półmat
Specification Applied:	EN ISO 5470-1
Date of Receipt of Test Item	05.07.2012
Date of Test:	09.08.2012
Date of Report:	10.08.2012
Page 1 of	3 text pages
Enclosures :	
Supplements:	
Total Number of Pages:	3
Number of Reports:	1

The test results relate only to the items tested.

Publication of this report in full or partly is only allowed with written authorization by MPA University of Stuttgart.

In case of doubt the German version is valid. Section 54180 "Sports surfaces, sports facilities",

Location: Pfaffenwaldring 4g, 70569 Stuttgart, Germany
Phone: int. 0049 711 685-63370 ; Fax: int. 0049 711 685-62765

1 Purpose of investigation

You commissioned us to test the wearing resistance of the lacquer **“Domalux Professional Poliuretan Aqua 1S pólmat”** according to EN ISO 5470-1. For the test we received one sample with the following dimensions 0,2 m x 0,7 m on 05.07.2012.

2 Testing procedure

The test was carried out according EN ISO 5470-1 (testing conditions: CS 10 wheels, load 500g, 1000 cycles).

Testing conditions: 23-50-2 according to DIN 50014.

3 Test results

The following test results were obtained.

Table 1: Test results

testing spot no.	loss of mass in mg
1	43,3
2	38,8
3	48,8
4	54,1
Mean	46,3

4 Evaluation

Basis for the evaluation is the requirement of EN 14904 regarding the loss of mass of coating and lacquers surfaces. The loss of mass shall be $\leq 80 \text{ mg} / 1000 \text{ cycles}$. With an average value of 46,3 mg this requirement was fulfilled by the lacquer "**Domalux Professional Poliuretan Aqua 1S pólmat**".

Prepared by



Volker Pietsch
Tester



Approved and released by



Dipl.-Ing. Rainer Wellhäußer
Vice Section leader